

ACCIDENT REPORT

This report is to be submitted against all accidents involving damage to aircraft and/or equipment or injury to personnel.

DATE OF ACCIDENT: May 30, 1961 TIME: 1530L STATION: Pa Daung

1. Aircraft Involved: Helicopter number HG

Extent of Damage: Destroyed - see MTS-SEA-61-91 for details.

2. Ground Equipment Involved: None

Extent of Damage: None

3. Personnel Involved: Wzabowski, Pilot Mateer - Co-pilot

Extent of Injury: Klock F/Mechanic

Both pilots killed F/Mechanic received superficial cuts and bruises.

Treatment:

4. Cause of Accident: Unknown

5. Corrective action being taken to preclude future similar accidents: None

6. Comments: See MTS/SEA-61-91

Distribution:
Vice President, Technical Services
Division Director
Department Chief
Section Manager/Superintendent
Safety Engineer
Insurance Co. Rep.
Director, Main Base

VPO
Wzabowski
Mateer

Klock P Files
Reported by: Jackson L. Forney
(Name and Title)

Date: June 4, 1961